


Guide pillar



Hardness: 58 ± 2 HRC.

b	a	d2	d1	L	QTY.

Notas: