


Tie bar with stop
 Tope guía
 Zderzak
 Guia limitador
 Colonne butee lisse



Hardness: 58 ± 2 HRC.

d1	d2	l2	a	R	L	REF.
14	20	18	8	M8	40	TGH/ 14 x 40 - M8
					50	TGH/ 14 x 50 - M8
					60	TGH/ 14 x 60 - M8
					80	TGH/ 14 x 80 - M8
					100	TGH/ 14 x 100 - M8
					125	TGH/ 14 x 125 - M8
					150	TGH/ 14 x 150 - M8
					175	TGH/ 14 x 175 - M8
					200	TGH/ 14 x 200 - M8
					M10	40
				50		TGH/ 14 x 50 - M10
				60		TGH/ 14 x 60 - M10
				80		TGH/ 14 x 80 - M10
				100		TGH/ 14 x 100 - M10
				125		TGH/ 14 x 125 - M10
				150		TGH/ 14 x 150 - M10
				175		TGH/ 14 x 175 - M10
				200		TGH/ 14 x 200 - M10

d1	d2	l2	a	R	L	REF.
20	26	25	10	M12	60	TGH/ 20 x 60 - M12
					80	TGH/ 20 x 80 - M12
					100	TGH/ 20 x 100 - M12
					125	TGH/ 20 x 125 - M12
					150	TGH/ 20 x 150 - M12
					175	TGH/ 20 x 175 - M12
					200	TGH/ 20 x 200 - M12
					225	TGH/ 20 x 225 - M12
					250	TGH/ 20 x 250 - M12
					M14	60
				80		TGH/ 20 x 80 - M14
				100		TGH/ 20 x 100 - M14
				125		TGH/ 20 x 125 - M14

